

PAKISTAN AERONAUTICAL COMPLEX, KAMRA
AVIONICS PRODUCTION FACTORY

TENDER NOTICE NO: APF/1920/42/LP/PC-23 DATED

NOVEMBER, 2017

1. SEALED TENDERS FROM PAC BOARD REGISTERED FIRMS FOR REPAIR OF UNDERMENTIONED ITEM IS INVITED.

PART NO	NOUN	QTY	UI	SCOPE OF WORK
NTDK20	SMALL SYSTEM CONTROLLER (SSC CARD)	01	EA	A) MAIN PROCESS ARE UNSERVICEABLE. B) ULTILAYER PCB DAMAGED AND NEEDS REPAIR. C) PROTECTION CIRCUIT AT SSC CARD DAMAGED AND NEEDS REPAIR. D) INPUT / OUTPUT PROTOCOL OF MAIN CONTROLLER APPLICATION CRASHED AND NEEDS TO BE RE-INSTALLED. E) SYNCHRONIZATION WITH CENTRAL PROCESSOR FAIL. F) SYSTEM NOT DEFINE THE CARD.

2. TECHNICAL AND COMMERCIAL OFFERS OF ABOVE MENTIONED ITEM MAY BE SUBMITTED IN SEALED ENVELOPES SEPARATELY TO **MD APF PAC KAMRA** ON “FOR” BASIS AND MAY BE DROPE IN **TENDER BOX NO. 01** PLACED ON MAIN GUARD ROOM APF BEFORE **1100 HRS ON 21 NOVEMBER, 2017. VALIDITY PERIOD OF QUOTATION MUST BE 90 DAYS MINIMUM** AND WILL BE OPENED ON THE SAME DAY AT 1130 HRS IN THE OFFICE OF DIR LOG (S&A), APF. GST MAY BE MENTIONED SEPARATELY AND EDD (EXPECTED DELIVERY DATE) MUST BE MARKED ON EACH QUOTATION. THIS FACTORY RESERVES THE RIGHT TO REJECT ANY QUOTATION ON TECHNICAL GROUNDS. ONLY REGISTERED SUPPLIERS, WHO ARE ON ACTIVE TAXPAYERS LIST, ARE ELIGIBLE TO QUOTE THE ABOVE MENTIONED SCOPE OF WORK. THE ENVELOPE MUST CLEARLY MENTION “**TENDER INQUIRY REF NO**” TO **DIRECTOR LOGISTICS APF**. FURTHER DETAILS / SCOPE OF WORK IF REQUIRED MAY BE OBTAINED FROM CONTACT NO 051-90992639, 2500 OR VISIT PAC WEBSITE **{www.pac.org.pk}**.



PAKISTAN AERONAUTICAL COMPLEX
A SYMBOL OF EXCELLENCE IN AVIATION

www.pac.org.pk



(TILAL MAZHAR)
FLIGHT LIEUTENANT
FOR MANAGING DIRECTOR
APF PAC KAMRA

Directorate of Logistic, APF, PAC Kamra



PAKISTAN AERONAUTICAL COMPLEX
A SYMBOL OF EXCELLENCE IN AVIATION

www.pac.org.pk

